

CHEVRON 60° I TECHNICAL INFORMATION

Product # 1176-4275-10





DESIGNER SOLUTION COLLECTION DECOR | NORTH CAPE

Wood species Oak Selection | Tavern Pattern | Chevron Constructions 3-layer flooring T&G Size |15x127x548 mm (5/8"x5"x21 9/16") Finish | Silk finish

CONSTRUCTION: 3-LAYER FLOORING T&G

DIMENSIONS :		litera.		PACKAGING:	BOX	PALLET
Thickness	15 mm (5/8")		5	Content	1,392 m2	54 box (75,168 m2
Width	127 mm (5")			Weigh	15 kg	804 kg
Length	548 mm (21 9/16")	Solid wood lamella 3,2 mm		HxWxL	155 x 275 x 675 mm	1080 x 832 x 2 050 mm
Cut angle	60°	Birch middle core 8,7 mm	7	Content	14,978 sq.ft.	808,808 sq.ft.
Microbevel		Solid wood lamella 3,1 mm	/ /	Weigh	15 lb	828 lb
Joint type	T&G	Cork compensators		HxWxL	6" x 11" x 27" mm	43" x 33" x 81" mm

DEVIATIONS:			
Deviation on Thickness	± 0,2 mm		
Deviation on Length	± 0,3 mm	EN 13489	
Deviation on Width	± 0,2 mm	FOCT 862.3	
Angle deviation of planks	≤ 0,25 mm		
Cup	≤ 0,2 % of width		
Bow	≤ 0,5 % of length	EN 13489	
Spring	≤ 0,1 % of length		

CHARACTERISTICS:			
Fire resistance	Dfl-s1		
Formaldehyde emission class	E1		
Pentachlorophenol content	None	EN 14342	
Thermal resistance	0,095 m2 K/W		
Thermal conductivity	0,158 W/(m·K)		
Structural warranty	Lifetime		

INSTALLATION:



Glue down over concrete, plywood or wooden subfloor or nail down over wooden subfloor. Applicable above, on and below ground level. Suitable for installation over radiant heating systems.

STORAGE AND USAGE:





Air humidity 40% – 65% — Temperature +18 °C – +22 °C

FINISH: SILK FINISH

DESCRIPTION	
Type of coating	UV-cured modified polyurethane-acrylate
Surface (finish) type	Semi-closed pores, wire brushed
Sheen	Silk matte 9-18 GU/85°
Finish warranty	-

CLASSIFICATION SURFACE CHARACTERISTICS:

Wear resistance	Not rated	EN 438-2
Scratch resistance	Not rated	EN 438
Slip resistance	50 (SRV dry)	EN 15676
Resistance to chemical agents	Class 5 (Except blue ink)	EN 13442
Repairability	Medium	

MAINTENANCE AND CARE CONDITIONS:

Maintenance of hardwood floors with Silk finish assumes regular (daily if necessary) cleaning from dust and grit using a vacuum, followed by a thorough cleaning with Coswick Hardwood Floor Cleaner or other similar product. Floor surface areas that receive the most traffic and get worn down quicker, such as areas by the front door, hallways, kitchens etc., should be periodically renewed with special Coswick Restorative Oil. This product restores the protective surface film. Frequency of use depends on type of interior and intensity of foot traffic. For residential interiors, restorative cleaning should be done once in 3-5 years; for public and commercial interiors with intense foot traffic, it is recommended to use the product 2-4 times a year.

SELECTION TAVERN

DESCRIPTION:		DESCRIPTION:	
Sound sapwood	Up to 25% of board width is allowed	Bark pocket	No limit (after filling)
Colour variation	Moderate contrast allowed	Pith	Permitted
Knot	Permitted big, filled	Slope of grain	Permitted
Cracks	Permitted wide, filled	Medullary ray	Permitted











